

ICC (ASC A117) CONSENSUS COMMITTEE ON ACCESSIBLE

Scoping – April 7 presentation – meetings TBD
Accessible bathing – April 21 presentation – meeting TBD
Accessible Communication Features for the Built Environment – meeting every other Wednesday, starting May 25, 1-3 Eastern
Walking and Wheeled Surfaces – meeting TBD

C. Administrative items

- 1) The revised proposals are available at - [A117.1 Public proposals 2-8-2022](#)
Information on the meetings and development of the 2023 edition of the standard will be posted at [A117.1 webpage](#)

D. ICC A117.1 development procedures - none

E) Review of Proposals:

1) Proposals:

The following proposals were decided during the call. Any items remaining on the agenda will roll to the next agenda -

04-11 w/ modification

- o Exp. 1 mod (20-4-4); AM (24-2-2);
- o Exp. 2 mod (23-0-2); 2nd mod (19-2-3); AM (13-7-5)

06-90-21 – Adult changing tables

Notes: Safety and performance information should address no sharp hazards under the table if it is folded up

613.4.1 some of the language is not enforceable. #3 and 5. If #1 is in 614.4.5, it is already addressed there. #8 need editorial clean up.

The requirements listed are to the for the entire system, not just the changing surface (613.4.1)

Modification to delete Section 613.4.1 26-3-0

AM (26-0-0)

04-12 – AS (5-18-3) D (23-1-1)

Notes: interior okay, need to address loads, but need specific from the door industry for loading

04-13 – hold till June 2 per Mike Tierney

04-14 – errata

Notes: this is a signage issue, not a side lite issue – could be addressed with better lighting, options for placement (especially in corridors with doors in recesses), education on signage for persons with low vision, clarification on placement of clear floor space in front of sign.

AS (1-23-2); D (26-0-1)

04-15

Notes: text needs to add gates because that is what this section covers; conflict with existing 404.3.8 for hardware; A156.19 is already addressed in 404.3, so this does not add anything

Mod to add swinging (25-1-0); AM (13-7-3)

04-16

Note: conflict with existing 404.3.8 for hardware; standards are already addressed in 404.3, how to you push or pull open automatic doors; what are the forces; what happens to gates?

Mod to add swinging (21-1-3); AM (7-13-6); D(20-5-1)

04-17 AS(17-5-2)

04-18 AS (23-0-0)

04-19 D(23-1-0)

04-20 – hold till